INFORMATION SHOWN ON THIS FORM IS SUBJECT TO MINOR CHANGES. OFFICIAL NRC REPORTS ARE SENT TO VNTSC ON A DAILY BASIS.

From: National Response Center

USCG HQ Washington, D.C.

1-800-424-8802 FTS 202-267-2675

To: MR FIELD

U.S. EPA X SEATTLE

Incident Report # 153210

INCIDENT DESCRIPTION

*Report taken by MST3 BESHOAR at 18:34 on 13-JAN-93

Incident Type: FIXED

Incident Cause: UNKNOWN

Affected Medium: LAND

Affected Area: SOIL

The incident was discovered on 07-JAN-93 at 12:00 local time.

REPORTING PARTY

Name:

KELLY STELKER

Organization:

WEYERHAUSER PAPER CO

Address:

POB 188

LONG VIEW, WA 98632

Day Phone:

(206)6367080

Type of Organization: PRIVATE ENTERPRISE

WEYERHAUSER PAPER CO called for the responsible party.

SUSPECTED RESPONSIBLE PARTY

Name:

KELLY STELKER

Organization:

WEYERHAUSER PAPER CO

Address:

POB 188

LONG VIEW, WA 98632

Day Phone:

(206)6367080

Type of Organization: PRIVATE ENTERPRISE

INCIDENT LOCATION

BASEMENT UNDER NO 4 PAPER MACHINE, 3401 INDUSTRIAL

HACHINE, STOT THEOSTICE

WAY

LONG VIEW, WA 98632

RELEASED MATERIAL(S)

CHRIS Code: PCB

POLYCHLORINATED BIPHENYLS

Qty Released: .00

UNK(S)

Qty in Water: .00

NON(S)

SOURCE/CAUSE OF INCIDENT

TRANSFORMER SUBSTATION/PCB CONTAMINATION DISCOVERED AT OLD TRANSFORMER SITE

2115

DAMAGE

Injuries:

Fatalities:

Evacuations:

County: COWLITZ

Damages:

REMEDIAL ACTIONS

NOTIFICATIONS BY CALLER

EPA: Y STATE: Y CG:

OTHER:

REMOVED CONCRETE FLOOR, WILL CONDUCT FURTHER CLEANUP

DESC: EPA X, DEC

NOTIFICATIONS BY NRC

U.S. EPA X SEATTLE 13-JAN-93 18:47 MR FIELD

ADDITIONAL INFORMATION

LEVEL OF CONTAMINATION HAS NOT BEEN DETERMINED

*** END INCIDENT REPORT # 153210 ***

USEPA SF 1424463